

SIMPLY CLEVER



Škoda Safety Day

A graphic element consisting of five red diagonal stripes, slanted to the right, positioned below the main title.



ŠKODA SAFETY DEMONSTRATION

CRASH RESULTS





TECHNICAL SPECIFICATIONS - YETI

Car: Škoda Yeti 2.0 TDI, 6-speed manual gearbox

Occupants: Driver: HIII front passenger: HIII

Left rear passenger: P3 Right rear passenger: P1.5





SUPERB COMBI

Car: Škoda Superb Combi, 2.0 TDI, 6-speed manual gearbox

Occupants: Driver: HIII, front passenger: HIII

Left rear passenger: P6, Right rear passenger: P3





PHOTO DOCUMENTATION OF DAMAGE SUPERB





PHOTO DOCUMENTATION OF DAMAGE - YETI





COMPUTER SIMULATION USING VIRTUAL CRASH 2.2



SIMPLY CLEVER




SIMPLY CLEVER



time: -0.030 s



SIMPLY CLEVER



time: -0.030 s

 **Škoda**
VÝZKUM DOPRAVNÍ BEZPEČNOSTI

SIMPLY CLEVER



Name,

9.9.2010

11

SIMPLY CLEVER




time: -0.030 s

 **Škoda**
VÝZKUM DOPRAVNÍ BEZPEČNOSTI




ASSESSMENT OF DUMMIES IN FRONT ACCORDING TO EURO-NCAP: ŠKODA SUPERB COMBI









ASSESSMENT OF CHILDREN ACCORDING TO EURO-NCAP







ASSESSMENT OF DUMMIES IN FRONT ACCORDING TO EURO-NCAP – ŠKODA YETI

HEAD + NECK		4.00
CHEST		4.00
PELVIS + THIGHS		4.00
SHINS		3.99
TOTAL	99.94%	15.99




ASSESSMENT OF CHILD DUMMIES ACCORDING TO EURO-NCAP

HEAD + NECK	4.00		4.00
CHEST	2.91		4.00
TOTAL		93.19%	14.91




STRESS ON DRIVER'S HEAD - ACCELERATION






STRESS ON DRIVER'S CHEST - COMPRESSION





FORCE IN DRIVER'S THIGHS



Force in thigh on the left/right

SIMPLY CLEVER



Škoda Safety Day

A graphic element consisting of five red diagonal stripes, slanted to the right, positioned below the main title.